GIPRO X-TYPE GEAR INDICATOR
Supplementary Manual

Honda CBR1100XX 2001-2006 (GPXT + GPX-H01)

Remove the seat.

Lift up or remove the fuel tank.

Route the GPX cable through the top opening of the Black dust boot.

Plug the GPX connectors in-line with the speed sensor connectors.

(White, 3-pole connectors in the Black dust boot at the left side below the fuel tank)

Connect the GPX Black/Green wire to the Yellow wire of the ECM/ECU.

(Gray connector, PIN #1, below the tail fairing near to the rear light)

GIPRO X-TYPE GEAR INDICATOR
Supplementary Manual

Typical position for the gear indicator.

Secure the unit properly.