OBD Tool
## Supplementary Manual

Secure the bike on a stand.

Remove the seats and the side fairings.

Locate the diagnostic connector.

(White, 6-pole connector)

OBD Tool
Supplementary Manual

Plug the OBD connector to the the diagnostic connector and the USB connector to the computer.

Turn the ignition key ON and click on the connect button in the program.

The faults shows on the screen.

OBD Tool
Supplementary Manual

To clear the faults:

First click on the Clear fault codes button
and then to the Yes button.

Start the engine if you wish to inspect
parameters with the engine running.