

GIPRO DS-SERIES GEAR INDICATOR Supplementary Manual


Honda CBR1000RR 2006-2007 (GPDT-H01)

Remove the left side middle fairing.



Connect the Gipro connector to the diagnostic system connector.

(Red, 4-pole connector with red cap near the fusebox)



Typical position for the gear indicator.

Secure the unit properly.

