

GIPRO X-TYPE GEAR INDICATOR

Supplementary Manual



Honda CBF600S 2004-2007 (GPXT + GPX-H01)

Secure the bike on a stand.



Remove the seats.

Remove the black plastic covers below the fuel tank.

Remove the side fairings.



Plug the GPX connectors in-line with the speed sensor connectors.

(Black, 3-pole connectors in a dust boot at the left side below the fuel tank)



GIPRO X-TYPE GEAR INDICATOR


Supplementary Manual



Honda CBF600S 2004-2007 (GPXT + GPX-H01)

Connect the GPX Black/Green wire to the Yellow wire of the Crankshaft Position Sensor connector.

(Blue, 2-pole connector in a dust boot on the left side below the fuel tank)



Typical position for the gear indicator.

Secure the unit properly.

(Shown with the optional Gipro Mount, part no.: GIPRO-M-BK)

