
GIPRO X-TYPE GEAR INDICATOR

Supplementary Manual



Honda CBR900RR 2000-2001 (GPXT + GPX-H01)

Remove the main seat.



Lift up or remove the fuel tank.



Route the GPX cable through the top opening of the Black dust boot.

Plug the GPX connectors in-line with the speed sensor connectors.

(Black, 3-pole connectors in the black dust boot below the fuel tank)



GIPRO X-TYPE GEAR INDICATOR

Supplementary Manual



Honda CBR900RR 2000-2001 (GPXT + GPX-H01)

Connect the GPX Black/Green wire to the Yellow wire of the ECM/ECU.

(Gray connector, PIN #1, below the main seat near to the battery)



Typical position for the gear indicator.

Secure the unit properly.

