GIPRO ATRE GEAR INDICATOR

Supplementary Manual



Kawasaki Z900 2017- (GPAT-K06)

Secure the bike on a stand.



Locate the Black, 3-pole gear position sensor connector near the shift linkage.



Remove the chain cover and route the GPAT G2 harness to the plug.




GIPRO ATRE GEAR INDICATOR

Supplementary Manual



Kawasaki Z900 2017- (GPAT-K06)

Plug GPAT G2 connectors inline with the gear position sensor connectors.



Connect GPAT G2 Red wire to the Brown/Yellow wire of the ABS indicator light at the 2-pole connector.



Typical position for the gear indicator.

