

GIPRO DS-SERIES GEAR INDICATOR Supplementary Manual



Honda CBF1000 2006-2012 (GPDT-H01)

Remove the main and passenger seats.

Remove the left and right black frame covers below the main seat and fuel tank.



Remove the metal connector holder above the airbox at the right side.



Connect the Gipro connector to the diagnostic system connector.

(Red, 4-pole connector with Red cap under the Black and White connectors at the right side.)



GIPRO DS-SERIES GEAR INDICATOR

Supplementary Manual



Honda CBF1000 2006-2012 (GPDT-H01)

Typical position for the gear indicator.

Secure the unit properly.

