GIPRO X-TYPE GEAR INDICATOR

Supplementary Manual



Honda CBF125 2009-2015 (GPXT + GPX-WSS)

Remove the fuel tank.



Mount the speed sensor.



Connect the GPX Black/Green wire to the Black/White wire of the ignition transformer.



GIPRO X-TYPE GEAR INDICATOR

Supplementary Manual




Honda CBF125 2009-2015 (GPXT + GPX-WSS)

Connect the GPX Red wire to the Grey wire of the headlight connector.

Connect the GPX Black wire to the Blue wire of the headlight connector.

(Black, 6-pole connector in a dust boot on the left side below the frame)



Typical position for the Gear Indicator.

Secure the unit properly.

