

Kawasaki Z1000 2003-2013 (OBD-K01)

Secure the bike on a stand.



Remove the seats.



Locate the diagnostic system connector.



OBd Tool

Supplementary Manual



Kawasaki Z1000 2003-2013 (OBd-K01)

Plug the OBd connector to the the diagnostic system connector and the USB connector to the computer.



Turn the ignition key ON and click on the connect button in the program.



Check the faults on the screen.

