

### Honda GL1800 Goldwing 2001-2007 (SH-V4 + SH-H01)

Secure the bike on a stand.

Remove the seat.


Remove the right side fairing pocket, heated hand grip control panel (where the lock for the right side fairing pocket is) and loosening of the top shelter is recommended to get to the connectors easily.



Locate the vehicle speed sensor connectors in a dust boot.



Plug the SpeedoHealer connectors in-line with the vehicle speed sensor connectors.



# SpeedoHealer

## Supplementary Manual



### Honda GL1800 Goldwing 2001-2007 (SH-V4 + SH-H01)

Typical position for the SpeedoHealer.

Secure the unit properly.

